

# Single Channel Process Indicator

## INDEX

### 1.Introduction

### 2.Specification

### 3.Installation

#### 3.2Key Functions:

#### 3.3Termination Board:

#### 3.4Connection Diagram :

### 4.Operation

#### 4.1 How To Set Zero /Span Range:

#### 4.2 How To Set Decimal Point:

#### 4.3 How To Set Alarm Value & Its Logic:

#### 4.4 How To Calibrate the Instrument :

#### 4.5 How To Set Modbus Connectivity:



## 1.INTRODUCTION

Single Channel Fix/Universal input Process indicator/controller/transmitter is designed to accept various types of inputs, & displays the process parameter through a 4 or 5 digit red LED display.

The instrument is available in a panel mounted housing which requires a cut out of 92mm(W) x 44 mm(H) x 85 (D)mm. A variety of power supply options are available for this.

The instrument employs low drift precision components for long trouble-free operation.

The instrument is a jumper-less system, there are different types of modes such as configuration mode, setup mode, calibration mode. Four keys provided can do any change in the mode. Default mode is normal mode.

## 2.SPECIFICATION


<b>Input</b>	: 4 to20 mA DC,k,b,e,t,s,r,n,j-Tc,PT100,PT46,0-10Vdc,CU53,
<b>Display Range</b>	: -1999 to 9999
<b>Display</b>	: 4 digit,(5 dgt optionally) red led, 12.5mm for PV Alarm status LEDs & Communication status LEDs.
<b>Accuracy</b>	: $\pm$ 0.25% for Linear Input,
<b>Power Supply</b>	: 24Vdc, 90 - 260Vac
<b>Ambient Temp</b>	: 0-50 deg C
<b>Dimensions</b>	: 48 mm (H) * 92 mm (W) * 85mm (D) Panel mounting, 96mm (H) * 96 mm (W) * 85mm (D)

### 3.INSTALLATION


The instrument is designed for mounting on a panel. It requires a cut out of 92 mm \* 44mm. Leave clear space of at-least 50 mm on top and bottom of the instrument for mounting the instruments from the back.

All field termination is done at the back of the instrument. The terminal strips are provided for the termination.

#### 3.1Key Functions:




#### 3.2 Termination Board:



- E** : EXIT Key  
 ↵ : Enter key / NEXT  
 ↑ : Increment key  
 ↓ : Decrement key

**Note:** To see Ambient temperature press down key (↓)

#### 3.3Connection Diagram :



### 4.OPERATION

#### 4.1 How to set Zero /Span Range:

Press Enter key  
 0000 (password, factory set is 0000)  
 Press Enter  
 Setp (setup menu)  
 Dp (press Up key select span)  
 Press Enter  
 100.0 (press up/ down key to set span value)  
 Press Enter  
 Press UP key  
 Zero ( zero value)  
 Press enter  
 0000 (press up/down key to set zero value)  
 Press enter

Press E (for Escape)

#### 4.2 How to set Decimal Point:

Press Enter key  
 0000 (password, factory set is 0000)  
 Press Enter  
 Setp (setup menu)  
 Dp  
 Press Enter  
 100.0 (press up key to shift decimal Point)  
 Press Enter  
 Press E (for Escape)

#### 4.3 How to set Alarm value & its logic:

Press Enter key  
 0000 (password, factory set is 0000)  
 Press Enter  
 Setp (setup menu)  
 Dp (press Up key select Alarm)  
 Press Enter  
 Rly 1 (press up/ down key to select 1,2,3,4 alarm)  
 Press Enter  
 L – ON (it will flash for type i.e Hi/Lo alarm select by UP/Down key)  
 Press enter  
 000.0 (it will flash for Setp i.e setpoint value set by up/down key desired value)  
 Press enter  
 000.0 (it will flash for hysteresis set desired value by up/down key)  
 Press enter  
 Rly 1 (select required alarm by pressing down key)  
 Press E for Exit

(follow similar procedure for other relays)

#### 4.4 How to change Password:

##### **PRESS**

Press **down key and turn on power supply**  
**Set old password by up and down**  
 Press '↵'  
**Set new password by up and down key**  
 Press '↵'  
 Press ESC KEY  
 TURN OFF POWER SUPPLY & RESTART IT.

##### **DISPLAY MESSAGE**

**opas**  
**xxxx**  
**npas**  
**xxxx**

#### 4.5 How to Calibrate the Instrument:

##### FOR RTD CALIBRATION ( for PT100,PT46,CU53 )

###### PRESS

###### DISPLAY MESSAGE

Press '↵' key and turn on power supply

**PASS**

Press '↵'

**0000**

Press '↵'

**CAL**

Press '↵'

**Inp**

Press '↵'

**t-c**

Press '↑' / '↓'

**rtd ( select rtd)**

Press '↵'

**C000**

( Set input as 0 degc i.e 100 ohms to make it zero value)

Press '↵'

**C350**

(feed 350 degc i.e 229.7 ohms at input terminal)

Press '↵'

**(hex value)**

Press '↑' / '↓'

**9999 or 0000**

Press '↑' / '↓'

**2297(set 2297)**

Press '↵'

Press 'E'

Ok

##### FOR THERMOCOUPLE (For all type of thermocouple)

Press '↵' key and turn on power supply

**PASS**

Press '↵'

**0000**

(k,b,e,t,s,r,k,j-tc)

Press '↵'

**CAL**

Press '↵'

**Inp**

Press '↵'

**t-c**

Press '↑' / '↓'

**t-c ( select thermocouple)**

Press '↵'

**zero**

( Set input as zero mv or short input terminals to make it zero value)

Press '↵'

**span**

(feed 50.00 mV at input terminal)

Press '↵'

**(hex value)**

Press '↑' / '↓'

**9999**

Press '↑' / '↓'

**5000(set 5000)**

Press '↵'

Press 'E'

Ok

##### FOR 0-10





40013 : Hysterasis2 Register  
40014 : Setpoint3 Register (LS Word)  
40015 : Setpoint3 Register (MS Word) (in case of 5 digit)  
40016 : Hysterasis3 Register  
40017 : Setpoint4 Register (LS Word)  
40018 : Setpoint4 Register (MS Word) (in case of 5 digit)  
40019 : Hysterasis4 Register  
40020 : ZERO Register (LS Word)  
40021 : ZERO Register (MS Word) (in case of 5 digit)  
40022 : SPAN Register (LS Word)  
40023 : SPAN Register (MS Word) (in case of 5 digit)  
40024 : ALARM1 TYPE  
40025 : ALARM2 TYPE  
40026 : ALARM3 TYPE  
40027 : ALARM4 TYPE  
End.....